


Suporte para Castanha



≥ Snut16



Snut12



	Castanhas	D	B	H	h	E	L	C1	C2	P	X	W	Y
SNUT12	1204	22,5	50	30	-	-	36	-	24	35	M5	32	M4
SNUT16	1605/1610	28	52	39.5	20	12	40	8	24	40	M5	38	M5
SNUT1616	1616	32	55	40	20	8	27	6	15	41	M4	42	M4
SNUT20	2005/2010	36	62	44	22	12	40	8	24	48	M6	47	M6
SNUT2020	2020	39	64	46	23	11	40	8	24	52	M6	50	M5
SNUT25	2505/2510	40	66	48	24	13	40	8	24	50	M6	51	M6
SNUT2525	2525	47	78.5	55	25.5	9	34	8	20	68	M6	60	M6
SNUT32	3205/3210	50	86	61.5	31	17	40	10	24	66	M8	65	M8
SNUT3232	3232	58	95	66	33	10	55	10	35	82	M8	74	M8
SNUT40	4005/4010	63	100	80	40	19	10	10	40	78	M8	78	M8
SNUT50	5010	75	116	85	42.5	22	46	10	26	92	M8	93	M8