


Suporte para Castanha



≥ Snut16



Snut12



	CASTANHAS	D	B	H	h	E	L	C1	C2	P	X	W	Y
SNUT12	1204	22,5	50	30,5	-	-	30,5	-	24	35	M5	32	M4
SNUT16	1605/1610	28	52	40	20	12	40	8	24	40	M5	38	M5
SNUT1616	1616	32	54	38	19	8	40	8	24	44	M5	42	M4
SNUT20	2005/2010	36	62	11	22	12	40	8	24	48	M6	47	M6
SNUT2020	2020	39	64	46	23	11	40	8	24	52	M6	50	M5
SNUT25	2505/2510	40	66	48	24	13	40	8	24	50	M6	51	M6
SNUT2525	2525	47	68	56	28	9	40	8	24	50	M6	60	M6
SNUT32	3205/3210	50	86	62	31	17	40	8	24	66	M8	65	M8
SNUT40	4005/4010	63	100	70	35	19	40	8	24	80	M8	78	M8
SNUT50	5010	75	116	85	42,5	22	46	10	26	92	M8	93	M8